

G 355735

REPAIR/R

Fault Report

ON/01795K

Customer Name: Rebar	Date: 03.06.24
Customer Reference: 355735 <i>Service call</i>	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Vision, Front bed RH	
Fault Description: Roller is moving left to right causing the fabric to fray on the control.	
Action to correct: N/A <i>1135 x 1130 Rimini B/o frost</i>	
Problem fixed on site: No	
Further action required: Debbie has images, repair or remake blind. Blind in the unit.	