

S356740  
MOSES / R

# Fault Report

Customer Name:      Date:    Moses 356704

Customer Reference: Fitter:

DAN

Salesperson:

Salesperson called: Yes  No

Blind Type and number:

Fault Description:

L/R Door

Slat on shutter cracked.

Action to correct:

re order slat

Problem fixed on site: Yes  No

Further action required:

Shutter slat cracked. please order replacement

liv side door bottom L/R side.  
(left)

all shutters fitted & called just slat to change

photos added.