


W

G355496

Laidler/R

Fault Report

Customer Name: Laidler	Date: 28.05.24
Customer Reference: 355496	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Shutter	
Fault Description: incorrect size shutter fabricated/ordered.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: See Graeme who has images, we think it needs 15mm off the drop and 15mm off the width as the window is shaped as below.	
	These sizes are the same throughout the window. They was also 1 white hinge pin missing on another shutter send some spares for all shutter components.