



Fault Report

Customer Name: Mitie	Date: 21/6/24
Customer Reference: 355725	Fitter: Dan
Salesperson: Dave	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: All 14 Blinds	
Fault Description: Should have been wand operation but have been made chain operation	
Action to correct: Re-make all headrails with wand operation	
Problem fixed on site: Yes/No	
Further action required:	