

S357204  
HUTSON/R

# Fault Report

Customer Name: HUTSON	Date: 05.11.24
Customer Reference: 357204	Fitter: SCOTT & DAN
Salesperson: SHAUN	Salesperson called: Yes/No YES
Blind Type and number: 2 X SHUTTERS	
Fault Description: - LIN BAY - SWAP LEFT DOOR TO MIDDLE AND MIDDLE DOOR TO LEFT SIDE ✓ BED SHUTTER LEFT DOOR HAS DENT ON (R) SIDE OF DOOR - NEW DOOR REQ'D - PICTURE SENT (DIFFICULT TO SEE)	
Action to correct: SEE ABOVE - 2 FITTERS REQ'D TO REMOVE FRAME AND MOVE T POSTS AND DOORS TO BE SWAPPED	
Problem fixed on site: YES/NO <u>NO</u>	
Further action required: RETURN & SWITCH DOORS AND ORDER NEW DOOR FOR BED SHUTTER	

\*Dan + Scott going back 25/11 to \*  
change doors over.