

G 355885  
Lovell / R

# Fault Report

Customer Name: Lovell	Date: 17/6/83
Customer Reference: 355885	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Roller	
Fault Description: Roller measured too big.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Roller needs to be 10mm smaller.	