

# Fault Report

FITTER NAME: GRAEME	FITTING DATE: 12-8-24
Customer Name: IRVING	
Customer Ref: 352447	
Salesperson: DAVE	Salesperson called: Yes/No
Blind Type and number: ITEM 5 (2ND 1/2 LANDING)	
Problem fixed on site: Yes/No	
Fault Description LOUVERS SENT ARE WRONG SIZE. LOUVERS NEED TO BE 408mm WIDE. CENTER OF STAPLE FOR TILT ROD MUST BE 196mm. 8 REQUIRED.	
Action to Correct:-	