

ON102407R

Fault Report

FITTER NAME: DANIEL	FITTING DATE: 07-08-24
Customer Name: HUTSON	
Customer Ref: 357174	
Salesperson:	Salesperson called: Yes/ <u>No</u>
Blind Type and number: VERTICALS	
Problem fixed on site: Yes/ <u>No</u>	
Fault Description 1 SLAT NOT SEALED PROPERLY 1 SLAT CREASED RUNNERS KISSING AT ENDS OF TRACK	
Action to Correct:- REMAKE 4 SLATS (COUPLE EXTRA)	