

G 358075
DULLING /R

Fault Report

FITTER NAME: Scott Johnson	FITTING DATE: 28.08.24
Customer Name: Dulling	
Customer Ref: 358075	
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Rollers	
Problem fixed on site: Yes/No	
Fault Description: Blind 1 motorised roller measured incorrectly. Blind 2 not fabricated.	
Action to Correct:- Cut down/Remake Blind 1, recess sizes Width 2300mm Drop 1000mm(Motor, remote, charger and brackets left on site). Fabricate Blind 2.	