

# FAULT REPORT

9359909

MILECASTLE  
PRIMARY  
SCHOOL //

<b>FITTER NAME:</b> Scott Johnson	<b>FITTING DATE:</b> 11.08.24
Customer Name: Milecastle Primary School	
Customer Ref: 359909	
Salesperson: Dan	Salesperson called: Yes/No
Blind Type and number: Sensory room, motorised roller in cassette	
Problem fixed on site: Yes/No	
Fault Description: Measured incorrectly. Too short on the width	
Action to Correct:- As Mentioned to Graeme I believe we could go back and pack the revels with timber and fix the bind into the timber revels then seal with caulk. Would need to be 2 man fit.	
Recess size: 1895mm width (top) 1905mm width (bottom). Drop will need cut on site as originally agreed.	

