

U 550004  
STODDART/R

# Fault Report

<b>FITTER NAME:</b> Dan	<b>FITTING DATE:</b> 13 November
Customer Name: Stoddart /	
Customer Ref: 358004	
Salesperson: Dave	Salesperson called: Yes/No Yes
Blind Type and number:  Rear bed shutter	
Problem fixed on site: Yes/No No	
Fault Description  Shutters measured incorrect	
Action to Correct:-  Please take 5mm from each side of shutter so can fit  Doors and accessories left on site with customer	