

Fault Report

FITTER NAME: Dan	FITTING DATE: 31st October
Customer Name: Job centre	/
Customer Ref: 356097	
Salesperson: Dave	Salesperson called: Yes/No Yes
Blind Type and number: All louvers	
Problem fixed on site: Yes/No No	
Fault Description All louvers measured to big at 1840 should be 1640 recess.	
Action to Correct:- 4 from 8 fitted due to damaging blinds when removing 4 full blinds to fit And 4 will just need to louvers changed. Remake all 8 sets of louvers	