

G358360

STAFFORD/R

ON/033SSR

# Fault Report

<b>FITTER NAME:</b> Scott Johnson	<b>FITTING DATE:</b> 12.02.25
Customer Name: Stafford	
Customer Ref: 358360	
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Roller, 1/2 Landing	
Problem fixed on site: Yes/No	
Fault Description: control keeps breaking due to weight of blind needs to be changed to a continues chain with p clip.	
Action to Correct:- send a continues chain (with P clip) to allow for the fitting height 3200mm which I believe the loop should be 1600mm (please disregard drop as the blind is face fixed and needs to be lower than the sill).	