

S357933

THOMPSON/R

ON/04/16/R.

# Fault Report

<b>FITTER NAME:</b> Scott Johnson	<b>FITTING DATE:</b> 06.03.25
Customer Name: Thompson	
Customer Ref: 357933	
Salesperson: Shaun	Salesperson called: Yes/ <input checked="" type="checkbox"/> No
Blind Type and number: Wood venetian, Landing	
Problem fixed on site: Yes/ <input checked="" type="checkbox"/> No	
Fault Description: Controls should have been right, right as ordered.	
Action to Correct:- Remake blind with correct controls, the blind getting took down is to be fitted in front bed right as agreed with office (£100) full balance to be paid on fitting £218 in total. Largest yellow steps are needed for this job.	



# SUNWOOD VENETIAN BLINDS

## Order Form

Company / Shop:	BAILEYS SMOOR	Sales Rep:	SHAUN H	Date:	11.02.25	Special Instructions:	CONTROLS TO BE ROOM LONG.
		Customer Name:	THOMPSON	Order Reference:	357933		

	BLIND SIZE & SYSTEM						CONTROLS				OPTIONS				
	Loc-ation	Width (mm)	Drop (mm)	Recess (✓)	Exact (✓)	Child-Safety Installation Height (mm)	Slat Width	Slat Range & Colour	Control Side			Tapes	Tassel	Valance	Fixing Brackets
									RHS (✓)	LHS (✓)	REV (✓)				
1	STAIRS	1758	1142	1/R		3500	50	REVERA	R			NO	STD	Y/B	STD
2															
3															
4															
5															
6															
7															
8															

NOTE: UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS RECESS AND ALL OPTIONS WILL BE DEFAULT.

FITTING NOTES: