

4 558900

LAIDLER / R

ON104612R

## Fault Report

<b>FITTER NAME:</b> Scott Johnson	<b>FITTING DATE:</b> 25.04.25
Customer Name: Laidler	
Customer Ref: 358900	
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Vertical, Bathroom	
Problem fixed on site: Yes/No	
Fault Description: Controls fabricated the wrong length. (too long)	
Issue: Fitting/Measuring/Office/Factory	
Separate Email for Photo's: Yes/No	
Action to Correct:- Remake head rail, all parts are on site and temporarily installed. Note the drop of the recess is 685mm so controls must be shorter with room to install the child safety.	