

G358810
Tamblin / R

Fault Report

Customer Name: Tamblin.	Date: 24.06.25.
Customer Reference: 358810	Fitter: Oan
Salesperson: Dave.	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: Shutter Bathroom slats.	
Fault Description: marks on 16 slats in bathroom 9 right door 7 on left photos added.	
Action to correct: re send new slats / re send both doors.	

Shutter Survey Sheet

Number of Shutters: 7 Survey Date: 13/3/25
 Survey Sheet: 1 Surveyor: DAVE
 Customer Name: TAMBLIN Fibres Required
 Order Number: 358810 Estimated Ft Fibres:

Item Number	Material	Colour	Room Name	Width	Drop	Mounting Type	Panel Quantity	Louvre Size	Tile Rod Type	Head Rail	Louvre Sill	Panel Configuration	Hinge Colour	Frame Type	No Of Sides	Sill Type	Field Out	Extras	Further Instructions	Further Instructions
2	BRUNO	TIMELSS	BRUNO	576	1463	FLUSH	1	76	GRSY	1050	NO	WHITE	WHITE	DEEP	4	41.3	41.3			
3	BRUNO	TIMELSS	BRUNO	576	1463	FLUSH	1	76	GRSY	1050	NO	WHITE	WHITE	DEEP	4	41.3	41.3			
4	BRUNO	TIMELSS	BRUNO	590	1463	FLUSH	1	76	GRSY	1050	NO	WHITE	WHITE	DEEP	4	41.3	41.3			
5	HUNGLOVE	TIMELSS	HUNGLOVE	1155	993	FLUSH	2	76	GRSY	NO	600	FR								

Panel Identification (Single Panel / All Panels)	63mm	75mm	88mm	114mm
New York	850/650	850/650	850/650	850/650
Los Angeles PVC	900/650	900/650	900/650	900/650
New York Max Config				
Los Angeles PVC Max Config				

Rebars Required Y/N

Rebar Size (M x C)	Length	Quantity
8x16x	1465	2

Order Information

Deposit Field

Customer Signature: _____ Date: _____

Surveyor Signature: _____ Date: _____