

558224

2

Fault Report

FITTER NAME: Dan	FITTING DATE: 12-06-25
Customer Name: Brown	
Customer Ref: 358554	
Salesperson: Dave	Salesperson called: Yes/No No
Blind Type and number: Kitchen 1 / bathroom shutters cover caps	
Problem fixed on site: Yes/No No	
Fault Description Kitchen 1 has pin hole / mark on sill plate will need to be replaced (photo) Bathroom - new shutter installed different to 1st shutter you can see previous Drilled holes in the sill as new one is narrower (Photo) Bathroom LH door damage to slat (photo) Bathroom rj leg damaged (due to me slipping with the drill as awkward angle And not being able to step in bath) (photo) Need also 8 screw cover caps in Perl to match frame	
Action to Correct:- Kitchen 1- replace sill plate photos added Bathroom will need new slat for door and new RH leg for the damage Cover caps needed in Perl to cover countersink holes on new shutter Unsure regarding seeing previous drilled holes as this shutter is made narrower Add some extra screws didn't want to do this until faults fixed	

*****All hinges and brackets have been change*****

Supply and fitting error