

U360673
Munley 1R.

Fault Report

Customer Name: Munley	Date: 14.11.25
Customer Reference: 360673	Fitter: Scott Johnson
Salesperson: Dave <i>Service call</i>	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Shutters, Bay 1(B1) Door, Bay 2(B2) left Door nr 2 (L2)	
Fault Description: Scratches on 8 slates in a continues line on both doors. See images on separate email. Some slates are loose and need tightened.	
Action to correct: assessment needed on scratches. Customer will tighten slates when he removes the curtain rail as some tightening screws are not accessible until this is done.	
	

