

G 361077
STEVENSUN/K

Fault Report

Customer Name: STEVENSON	Date:
Customer Reference: 361077	Fitter: DAN
Salesperson: DAVE	Salesperson called: Yes/No <input checked="" type="checkbox"/>
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No <input checked="" type="checkbox"/>	
Blind Type and number: INFUSION WOOD (LOOK WHITE) X1	
Fault Description: NO TAPES ON BACK BED (R.H.)	
Action to correct: SUPPLIER ERROR - BLIND TO BE RE-MADE	