

348270

# Fault Report

Customer Name: Herrington	Date: <del>19.05.25</del> 14/01/24
Customer Reference: 348270	Fitter: Scott Johnson
Salesperson: Walker <i>Service call</i>	Salesperson called: Yes/ <b>No</b>
Order Inputting Error	Mismeasure
Production Error	<b>Supplier Error</b>
Fitting Error	
Problem fixed on site: Yes/ <b>No</b>	
Blind Type and number: Blind 6 Motorised roller	
Fault Description: Motor not holding charge.	
Action to correct: Order new motor.	