

360028

Fault Report

Customer Name: Williams	Date: 02.02.26
Customer Reference: 360028	Fitter: Scott Johnson
Salesperson: Shaun	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Vertical, Dining room	
Fault Description: slats measured to long.	
Action to correct: Order new slats @1145MM DROP	