

361593

Fault Report

Customer Name: Bolam	Date: 05.02.26
Customer Reference: 361593	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: <input type="checkbox"/> Yes/ <input type="checkbox"/> No
Order Inputting Error	<input type="checkbox"/> Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: <input type="checkbox"/> Yes/ <input type="checkbox"/> No	
Blind Type and number: rollers, Con 1 & 3	
Fault Description: Con 1 measured to long, Con 3 bottom bar incorrect see images attached.	
Action to correct: Remake Con 3 with exposed white bottom bar as ordered, Con 1 is in unit van be cut down or remade. Bracket to bracket size is 2500mm	