

② Fault Report

FITTER NAME:	SCOTT	FITTING DATE:	15/01/26
Customer Name:	THOMPSON		
Customer Ref:	360206		
Salesperson:	SHAUN	Salesperson called: Yes/No	Yes
Blind Type and number:	1x ROLLER		
Problem fixed on site: Yes/No	No		
Fault Description	CUSTOMER NOT HAPPY WITH STITCHING ABOVE BOTTOM BAR (EXTRA HOLES ON (L) SIDE ABOVE STITCHING)		
Action to Correct:-	FIX BLACK L29 LOOP BRAID TO COVER STITCHING ABOVE BOTTOM BAR AND RETURN TO CUSTOMER (POLE ON SITE AT CUSTOMERS)		