

356559

# Fault Report

<b>FITTER NAME:</b> Dan	<b>FITTING DATE:</b> 27 Feb 20
Customer Name: Stooperdale offices	
Customer Ref: 356559	
Salesperson: Dan	Salesperson called: Yes/No Yes
Blind Type and number:  Roller blind room R1-11 roller left	
Problem fixed on site: Yes/No <b>No</b>	
Fault Description  Blind measured wrong the recess at top is much smaller than at bottom	
Action to Correct:-  Please cut blind down to 1440 recess size all brackets are fitted and child Safety is on the window cill. Blind sent back up to Scotland on Friday  All other blinds from phase 1 and phase 2 also ICT post room and print room Are all fitted and complete.  Small set of steps required to fit as it's a window cill blind that you can stand on	