

G 3601364

# Fault Report

Customer Name: Robinson	Date: 06.03.26
Customer Reference: 361364	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: perfect fit pleated, blind 1	
Fault Description: Incorrect bracket size ordered.	
Action to correct: 20mm anthracite needed for blind 1 not 28mm, temporary white brackets installed, please order 20mm anthracite brackets to replace the white ones.	