

G 361487

Fault Report

Customer Name: Ashcroft	Date: 10.03.26
Customer Reference: 361487	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Shutters, LH front bedroom 1 & 2	
Fault Description: widths measured too small.	
Action to correct: Order new shutters @ 1130mm width, Shutters have been temp fitted for covering as discussed with Greame. On revisit time is needed for removal also a 2 man fit.	