

G 361645

Fault Report

Customer Name: Kane	Date: 11.03.26
Customer Reference: 361645	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Wood Venetian, Front lounge	
Fault Description: Drop measured incorrectly.	
Action to correct: Order new blind with 1150mm Drop. Blind fitted for privacy.	