

G 361617.

Fault Report

Customer Name: Lynas	Date: 20.03.26
Customer Reference: 361617	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Curtains	
Fault Description: measured too short on the drop.	
Action to correct: Dave to revisit and remeasure as discussed with Dave, pole left with customer, curtains will be returned to unit on Thursday 26th march when I return to work.	

