

G3611do5

Fault Report

Customer Name: Ashe	Date: 27.03.26
Customer Reference: 361665	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Roman, rear bedroom	
Fault Description: control end damaged, see images.	
Action to correct: send new control end with built-in child safety, to be fit on site. P clip needs installed after replacing the control end.	