

G 3601687

Fault Report

Customer Name: Page	Date: 15.04.26
Customer Reference: 361687	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Curtain, Bed bay	
Fault Description: Fabricated incorrectly (Width)	
Action to correct: Remake Curtains the width measured (3600mm). I've temporarily put one side of the Study curtains up in the bed room for a temporary covering.	