

G361535

Fault Report

Customer Name: Radichi	Date: 15.04.26
Customer Reference: 361535	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Shutter bay	
Fault Description: Measured incorrectly (Width)	
Action to correct: Send Dave out to remeasure, Bay 1 40mm too wide Bay 2 80mm too wide Bay 3 40mm too wide The above are rough sizes.	