

G361442

Fault Report

Customer Name: Williams	Date: 22.04.26
Customer Reference: 361442	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Shutters	
Fault Description: Customer needs work done around the window after they removed the battons that was agreed with Dave at point of sale.	
Action to correct: Once customer has had the work completed they will call to rebook, dinner and front bedroom fitted but not caulked as remedial works needed done around the windows, lounge has been returned to the unit. 1 shutter to fit and 3 shutters to caulk.	