



BOYDS BLINDS LTD
 11 Woodland Drive
 Southwell
 Nottinghamshire
 NG25 0DA
 01158740916
 info@boydsblinds.co.uk
 www.boydsblinds.co.uk
 VAT Registration No.: 998906143

QUOTE

Job Number:
 BOY11619

Quote Date:
 Wednesday 04 Sep 2024

To:
 Mrs.Ellen Grogan
 124 Trent Boulevard West Bridgford
 Nottingham NG2 5BL
 Mob: 07875399856

Job Address:
 Mrs.Ellen Grogan
 124 Trent Boulevard West Bridgford
 Nottingham NG2 5BL
 Mob: 07875399856

Description	Unit Price	Net Price
Products		
Blackout Roller Blind (Velux) Quantity: 2, Supplier: Velux, Windows Type: GGL, Window Size: UK08,UK08,UK08, Operation Method: Mains Powered, Colour: 1025, Product Type: A1, Side Rail Finish: White Painted Aluminium	212.00	424.00
Blackout Roller Blind (Velux) Quantity: 1, Supplier: Velux, Windows Type: GGL, Window Size: UK04, Operation Method: Mains Powered, Colour: 1025, Product Type: A1, Side Rail Finish: White Painted Aluminium	196.00	196.00
Blackout Roller Blind (Velux) Quantity: 1, Supplier: Velux, Windows Type: GGL, Window Size: 304, Operation Method: Manual, Colour: 1025, Product Type: A1, Side Rail Finish: White Painted Aluminium	84.00	84.00
Repair/Call out fee Quantity: 4, Extras: Call out or repair fee, Special Instructions: Fitting fee	25.00	100.00

Subtotal: £ 804.00
 VAT: £ 160.80
 Total: £ 964.80
 Deposit: £ 0.00
 Balance: £ 964.80

If you wish to proceed with this estimate, please contact the office on 01158740916 to discuss payment for your 50% deposit.
 If paying by BACS, please use the above job number as your reference and pay to the below bank details
 BACS - BANK - NATWEST, Account - 36082430, Sort code - 60-20-15

****Terms & Conditions of Sale**

If you proceed with the order then you are agreeing to all the below terms and conditions.

You are agreeing to pay the amounts shown above on completion of the blinds being fitted.

Due to the products being made for your specifications only, if you cancel the order then the deposit will not be returned.

When fitting your products you should be aware that some materials may splinter or crack due to their nature. We can not be held responsible if this is the case and it is at the customers own risk.

Child Safety - All blinds must be fitted with a safety device to secure cords and chains to limit the risk of injury.