

L'HORIZON HOTEL

WEINOR PERGOTEX II ROOF SYSTEM SERVICING SHEET

Maintenance carried out by CP Interiors during quarterly service

Service Sheet Signed: D. Baird

DATE SERVICE CARRIED OUT: 16/07/21

Unit NO	1	2	3	4	5	6	7	8	9	10	11	12	13
1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	Change pulley	Change pulley
5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Comments	Dirtyest its ever been 2 x heaver pulleys needs replacing + 1x element pullys on last 2 are very squeaky To find again, All company documents, General, Templates + forms,												