

SB 7207
MCGUIRE/R1

SCOT BLINDS Fault Report

Customer Name MCGUIRE	Date: 16-2-26
Customer Reference: 7207/R	Filter DAVID
Salesperson: RONNIE	Salesperson called: Yes/No
Fault Description: NO SPLIT IN THE SLATS LIV R SHUTTER	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEW DOOR NEEDED FOR THE LIV R SHUTTER WITH THE SPLIT IN THE SLATS AT 500 REMEMBER ITS THE REMARK SIZE AND CONFIGURATION NOT THE ORIGINAL	

ORDER TOTAL = 1268.00
DEP PD = 7/7/25