

Fault Report

Customer Name: Macdonald	Date: 28/3/24
Customer Reference: 6650/5654	Fitter: David
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Shutter rh door (sons room/front top right room)	
Fault Description: Bottom 3 slats broken on the last rh panel	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: 3 new slats needed. Told to put in fault report as we need to get a price for the slats	