

Fault Report

Customer Name: Paterson	Date: 23/2/22
Customer Reference: 6116	Fitter: Mike
Salesperson: Mark E	Salesperson called: Yes/No
Blind Type and number: 1, 2, 4, 5 & 7	
Fault Description: 1 + 2 - Blind width too tight by 3-4mm (in middle) 4 + 5 - As above also wand on 5 on wrong side 7 - Wand on wrong side of blind.	
Action to correct: 1, 2, 4 + 5 - Either remake slightly narrower or cut down float rail in blind as slats clear ok. 5 + 7 - Wands on wrong side - Remake?	
Problem fixed on site: Yes (No)	
Further action required: Discuss - Pics available - happy to explain more on phone.	