

Fault Report

Customer Name: Smith	Date: 29/7
Customer Reference: 5682	Fitter: Mike
Salesperson: Marc e	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: 3 x Into BF	
Fault Description: Headrails too wide - doesn't allow windows to operate.	
Action to correct: Reduce headrails by 10mm each side.	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Further action required:	