

# Fault Report

Customer Name: CAIROL	Date: 7-12-22
Customer Reference: 6340	Fitter: DAVID/ARCAME
Salesperson: MUKL	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: SHUTTER 2 & 3	
Fault Description: SHUTTER 2 - RH DOOR (DAMAGED ARCAME HAS PICTURE) SHUTTER 3 - RH INSIDE INSERT MISSING (SIDE CHANNEL)	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New DOOR NEEDED + New INSERT/SIDE CHANNEL NEEDED	