

GC 6268
Radford IR.

Fault Report

Customer Name: Radford	Date: 19/7/22
Customer Reference: 6268	Fitter: Mike
Salesperson: Mike	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: Weights not sealed into slats.	
Action to correct: 10 new slats required. Recess Weight 1255	
Problem fixed on site: Yes/No	
Further action required:	