

GC 6484
McLaren/R.

Fault Report

Customer Name: McLaren	Date: 4-11-22
Customer Reference: 6484	Fitter: DAVID
Salesperson: MARK E	Salesperson called: Yes/No
Blind Type and number: 1 3 VERTICAL	
Fault Description: MIS MEASURE	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: New SLATS needed FOR BLINDS 480 x 1185	

