

GC 6606

Fault Report

Customer Name: ROSCERS	Date: 17-11-22
Customer Reference: ROSCERS 6606	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: 1080 TRACK	
Fault Description: TRACK DAMAGED/PAINT CHIPPED (3410)	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEW TRACK NEEDED	