

# Fault Report

Customer Name: MALCOLM	Date: 17-11-22
Customer Reference: 6381	Fitter: DAVID
Salesperson: MIKE	Salesperson called: Yes/No
Blind Type and number: 1 Motorised Roller	
Fault Description: CHARGING POLE DAMAGED ON MOTOR BOTTOM BAR ROTTING SQUINT	
Action to correct: <del>REPAIR</del> R	
Problem fixed on site: Yes/No	
Further action required: New motor BOTTOM BAR Re Done	