

CC 6659

Fault Report

Customer Name: MILLAR	Date: 16-12-22
Customer Reference: 6659	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: 2 INTO MICRO	
Fault Description: NOT ENOUGH SIDE CHANNEL CLIPS IN PARK	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEED 6 NEW SIDE CHANNEL CLIPS FOR TYPE (D)	