

GC 6411
CAMPBELL.

Fault Report

Customer Name: CAMPBELL	Date: 13-4-23
Customer Reference: G411	Fitter: DAVID
Salesperson: MIKE	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: LIVING ROOM SHUTTER AT 1660 WIDE DOOR 3	
Fault Description: 2 SLATS NOT TURNING CORRECTLY WITH OTHER SLATS	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: UNSURE IF NEEDS NEW DOOR OR JUST NEW SLATS VIDEOS SENT TO GRAHAM	