

QC 6777
BURNSIDE

Fault Report

Customer Name: Burnside	Date: 21-4-23
Customer Reference: 6777	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: VCLX 1A2	
Fault Description: WRONG COLOUR OF FRAME	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: FRAMES are supposed to be white	