


# Fault Report

Customer Name: TAYLOR	Date: 27/7/23
Customer Reference: CC6913 TAYLOR 1R	Fitter: DAVID H
Salesperson: DAVID H	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: Slats made too short by factory	
Action to correct: Re-make slats again	
Problem fixed on site: Yes/No	
Further action required:	

# RAINBOW BLINDS

61 Canyon Road  
Excelsior Park  
Wishaw  
ML2 0EG

email: 01698 351888 TEL NO  
01698 351999 FAX NO



# Vertical order form

<b>Customer Name:</b>	GOLDCREST FURNISHINGS
<b>Delivery Address:</b>	GOLDCREST FURNISHINGS SPRINGKERSE BUSINESS PARK UNIT2 STIRLING FK7 7GN 01786 447647

<b>Order No:</b>	ON61867
<b>Date:</b>	31-07-2023
<b>Date Req:</b>	03-08-2023
<b>Customer Ref:</b>	GC 6913 TAYLOR / R
<b>Contact:</b>	

Blinds No	Qty	Width	Drop	Fitting Height	Product Type	Fabric	Colours
1	1	1750 mm	2110 mm	2200 mm	89mm Slats Only discount applied B	Polaris B/O (A)	Charcoal
<b>Blind or Recess</b>		<b>Control Side</b>	<b>Bunch</b>	<b>System Type</b>	<b>Headrail Color</b>	<b>Fixing Brackets</b>	<b>Location</b>
Recess		LHC	LH	System Vogue	White	Top Fix	DOORS
<b>Further Instructions</b>							
SLATS ONLY PLEASE							

*Supplier (other) Products  
Slats too short*