

GC 6945
GUNTHER/
R

Fault Report

Customer Name: Gunther	Date: 19-7-23
Customer Reference: 6945	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: PF Roller Roller 1+2	
Fault Description: PF FRAME NEEDS TO BE CUT OUT TO BE REMOVED IN FOR THE FRAME TAKEN IN FURTHER. MIS MEASURE FOR BLINDS 1+2	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: FRAME NEEDS CUT FURTHER IN. REMAKE BLINDS 1+2 AT 1340 width AND CASSETTE AT 2680 1340	