

Fault Report

Customer Name: FLYNN	Date: 24/08/23
Customer Reference: EC 6849	Fitter: DEREK CONROY
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: P/FIT ROLLER. RH DOOR.	
Fault Description: BUND ROLLING UP SQUINT AND HAS STRETCHED FABRIC, FABRIC NEEDS REPLACED EXACTLY AS IS. TO MATCH LH DOOR.	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:	