

Fault Report

Customer Name: wilson Customer Reference:	Date: 9/11/23 Fitter: david
Salesperson: mike Blind Type and number: Perfect fit roller	Salesperson called: Yes/No
Fault Description: Left door pf roller material has been made smaller than the right door when both should be the same size Makes the roller come out of the runners	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: Remake the left door to the same size as the right door	